

School Environmental Health Inspection Report

*Tabled by the
Minister of Education
2023-05-25
Dunn*

1 School Croft Roberts International Principal Grace Macdonville
 Location Country Access Rd.
 Grades 7-9 No. of Students 665 Type of Inspection Routine Complaint Follow-up Other

2 LEGEND: S - Satisfactory U - Unsatisfactory N/A - Not Applicable NOB - Not Observed R - Repeat Observation

	S	U	N/A	NOB	R		S	U	N/A	NOB	R		S	U	N/A	NOB	R
1 School Grounds and Exterior						8 Home Economics Room	<input checked="" type="checkbox"/>					15 Science Rooms and Laboratories					
2 Outdoor Play Spaces						9 Auditoriums						16 Solid Waste Disposal					
3 Indoor Air Quality						10 Student Dining Area			<input checked="" type="checkbox"/>			17 Custodial Activities	<input checked="" type="checkbox"/>				
4 All Indoor Environments						11 Library/Media Room						18 Mechanical Rooms					
5 Attics, Mezzanines, Basements and Crawl Spaces						12 Gymnasium						19 Drinking Water					
6 Washrooms and Showers						13 Visual Arts Classrooms						20 Sewage Disposal					
7 Music Room						14 Industrial Arts Rooms						Food Safety: See Food Premises Inspection Report, if applicable					

3 Observations and Corrective Actions Compliance Time

Problem was confirmed by the principal

- Termite on site, remediation ongoing*
- Traps set throughout the school*
- Chickens were displayed from in all "balks"*
- Kitchen school lunch hall food kept in containers and/or fridge. (Home Econ room, food removed)*
- * - 0 staff should use appropriate PPE when cleaning rodent droppings*
- children eating in classrooms and hallways creates extra clean up for staff*
- IF rodent droppings are noted on desks in the morning - sanitize surfaces before students enter.*

4 Environmental Health Officer's Signature [Signature] Date 2023-05-10 School Administrator/Designate [Signature] Date 2023-05-10

Note: Environmental Health Officers (EHOs) conduct school inspections to identify potential risks to the health and safety of students, staff and the general public. The School Environmental Health Inspection Report is used by EHOs during the annual school inspection. The Guide to School Inspections for Environmental Health Officers is used as a reference for any health and safety risk within the school environment. The Guide is not a set of school standards/regulations. The exception is the identification of public health hazards related to food safety, drinking water quality and sewage disposal. These exceptions are regulated under the Food Premises Act and the Health and Community Services Act.



Toll Free: 1-800-563-5471 **INSPECTION / OFFICER'S REPORT**
Accident Reporting: 729-4444

Reference #: 0770846
Inspection: MAY 12, 2023
MAY 15, 2023

EASTERN REGION (NL ENGLISH SCHOOL BOARD)
215 WATER ST, SUITE 601
ST. JOHN'S
NL

Firm #: 370026
WCC #: 2020611
Tel: 709-758-2372
Fax: 709-753-4973

A1C-6C9

Worksite: Frank Roberts Junior High
Location: Foxtrap
Employer Co-Chair: John Williams

Employees: 40
NIC: 8511
Insp. Time: 11:00AM

████████████████████ 40 (1)

Worker Rep/Designate: N/A

Attention OHS Committees

"As of January 1, 2022, all OHS Committees will be required to submit meeting minutes through CONNECT. For more information, contact us at ohs.minutes@workplacenl.ca or call 709.778.1552 and select option 3."

REPORT

I arrived on site at 11:00 accompanied by Officer Glenn Coates. The purpose of this inspection was to investigate a complaint regarding rodents and air circulation. Once on site, we met with Bruce Mandeville, Principal, and Jonathan Williams, Assistant Principal, and the complaint was discussed followed by a walkthrough of the school.

In the complaint received, there was discussion of rodent issues including feces being found in classrooms and evidence of rodents in several areas of the school. Mr. Mandeville stated that rodents have in fact been an ongoing concern. Terminix have been on site regularly to work on getting the issue under control. It was reported that Terminix believes that mice are currently the issue, not rats. They have traps set up throughout the school and maintenance is now removing traps during the day (when students are in school) and replacing them in the evening. There were no traps noted in the hallways or classrooms today for that reason. If rodent droppings are observed, custodial staff are made aware and they do the cleanup. Teachers are not required or expected to clean up droppings. A written procedure for cleanup of droppings is being requested at this time. Also, a copy of service reports detailing what work has been done to date by Terminix as well as an action plan detailing what is to be done moving forward must be provided.

Another complaint made involved poor air circulation due to the inability to open windows. During today's inspection most of the windows on the front of the building were observed to be open but a few were closed because the screen was missing. In order to comply with the school's own natural ventilation protocol, all screens must be replaced as soon as possible after being damaged or removed to ensure that the windows can be opened for the minimum required amount of time.

Water infiltration through the ceiling was another concern brought up. Mr. Mandeville and Mr. Williams stated that there have been a few areas where water has been able to infiltrate the building. They took us to all areas of concern. There were no active leaks observed during today's visit and upon inspection of

A copy of this inspection/order report must be provided at the earliest possible opportunity to your OHS Committee, Worker Representative or Workplace Designate.